



External Wall Leakages



SEVERITY

High
Moderate
Low

Type of Damage / De

- Observed major leakages and Expansion Joint
- Negative grouting at so be taken before positive waterproofing coatings

Possible cause

- Observed major leakages and Expansion Joint
- Negative grouting at so be taken before positive waterproofing coatings

Suggested Products /

- Observed major leakages and Expansion Joint
- Negative grouting at so be taken before positive waterproofing coatings