


External Wall Leakages



SEVERITY

- High
- Moderate
- Low

Type of Damage / De

- Observed major leakages and Expansion Joint
- Negative grouting at so be taken before positive waterproofing coatings

Possible cause

- Observed major leakages and Expansion Joint
- Negative grouting at so be taken before positive waterproofing coatings

Suggested Products /

- Observed major leakages and Expansion Joint
- Negative grouting at so be taken before positive waterproofing coatings

